

TEST CERTIFICATE

Customer Name Roy Corneloues Misc Audio Equipment	Address Tested on site (PLRS) Unit 1 Grove Holdings, Grove Road, Little Clacton, Essex CO16 9NG	Company Name: PLRS Sound System & Stage Hire Tester Name: Peter Lucken	Test Instrument Details Make / Model: Siemens 1000 PT/2 Serial No.: 4502185557630
--	---	---	--

No	Date	Description	Serial No	Location	Visual	Polarity	Earth Bond	Class	Insulation	Leakage	Flash	Load KVA	Result	Retest
1	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
2	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
3	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
4	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
5	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
6	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
7	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
8	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
9	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
10	28/07/18	25m reel 13A			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
11	28/07/18	25m reel 13A			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
12	28/07/18	20m reel 13A			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
13	28/07/18	6 gang extension			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
14	28/07/18	6 gang extension			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
15	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
16	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
17	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
18	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
19	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
20	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
21	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
22	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
23	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
24	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
25	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
26	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19

TEST CERTIFICATE

Customer Name Roy Corneloues Misc Audio Equipment	Address Tested on site (PLRS) Unit 1 Grove Holdings, Grove Road, Little Clacton, Essex CO16 9NG	Company Name: PLRS Sound System & Stage Hire Tester Name: Peter Lucken	Test Instrument Details Make / Model: Siemens 1000 PT/2 Serial No.: 4502185557630
--	---	---	--

No	Date	Description	Serial No	Location	Visual	Polarity	Earth Bond	Class	Insulation	Leakage	Flash	Load KVA	Result	Retest
27	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
28	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
29	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
30	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
31	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
32	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
33	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
34	28/07/18	Clover IEC			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
35	28/07/18	6 gang surge protection			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
36	28/07/18	6 gang surge protection			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
37	28/07/18	Figure 8 Power lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
38	28/07/18	Figure 8 Power lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
39	28/07/18	4m 13A extension			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
40	28/07/18	4m 13A extension			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
41	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
42	28/07/18	Figure 8 Power lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
43	28/07/18	Magsafe charger			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
44	28/07/18	Figure 8 Power lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
45	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
46	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
47	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
48	28/07/18	Tab charger			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
49	28/07/18	Tab charger			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
50	28/07/18	Figure 8 Power lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
51	28/07/18	Figure 8 Power lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
52	28/07/18	16v AC/DC adapter			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19

TEST CERTIFICATE

Customer Name Roy Corneloues Misc Audio Equipment	Address Tested on site (PLRS) Unit 1 Grove Holdings, Grove Road, Little Clacton, Essex CO16 9NG	Company Name: PLRS Sound System & Stage Hire Tester Name: Peter Lucken	Test Instrument Details Make / Model: Siemens 1000 PT/2 Serial No.: 4502185557630
--	---	---	--

No	Date	Description	Serial No	Location	Visual	Polarity	Earth Bond	Class	Insulation	Leakage	Flash	Load KVA	Result	Retest
53	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
54	28/07/18	IEC 13A Lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
55	28/07/18	1 IECin to 3 IEC out			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
56	28/07/18	1 IECin to 3 IEC out			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
57	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
58	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
59	28/07/18	IEC to IEC link lead			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
60	28/07/18	IEC splitter			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
61	28/07/18	IEC splitter			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
62	28/07/18	IEC splitter			Pass	Pass	Pass	1	Pass	Pass	N/A	Pass	Pass	28/07/19
663	28/07/18	ASR Powered Speaker Unit			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
664	28/07/18	ASR Powered Speaker Unit			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
665	28/07/18	Alto Sub Speaker			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
666	28/07/18	Alto Sub Speaker			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
674	28/07/18	Acme Super Leo			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
675	28/07/18	Acme Super Leo			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
676	28/07/18	Acme Super Leo			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
678	28/07/18	Acme Super Leo			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
680	28/07/18	Acme Magic Gobo			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
681	28/07/18	Acme Magic Gobo			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
682	28/07/18	Eurolive E1520			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
683	28/07/18	Acme Magic Gobo			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
684	28/07/18	Acme Magic Gobo			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
685	28/07/18	Eurolive E1520			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
686	28/07/18	Samson Powered Sub Speaker			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
687	28/07/18	Samson Powered Sub Speaker			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19

TEST CERTIFICATE

Customer Name Roy Corneloues Misc Audio Equipment	Address Tested on site (PLRS) Unit 1 Grove Holdings, Grove Road, Little Clacton, Essex CO16 9NG	Company Name: PLRS Sound System & Stage Hire Tester Name: Peter Lucken	Test Instrument Details Make / Model: Siemens 1000 PT/2 Serial No.: 4502185557630
--	---	---	--

No	Date	Description	Serial No	Location	Visual	Polarity	Earth Bond	Class	Insulation	Leakage	Flash	Load KVA	Result	Retest
793	28/07/18	KAM LED Partybar			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
794	28/07/18	KAM LED Partybar pedal			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
795	28/07/18	KAM LED Partybar			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
796	28/07/18	LED Par bar			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
797	28/07/18	Kam Receiver 1			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
798	28/07/18	Kam Receiver 2			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
799	28/07/18	Behringer EQ			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
800	28/07/18	Behringer 8 channel mixer			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
801	28/07/18	Power distribution unit			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
802	28/07/18	Pioneer CDJ			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
803	28/07/18	Pioneer CDJ			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
804	28/07/18	Gobo Projector			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19
805	28/07/18	Star cloth controller			Pass	Pass	Pass	2	Pass	Pass	Pass	Pass	Pass	28/07/19